



Gorbel Work Station Bridge Crane Helps Increase Speed and Safety

Since installation they have doubled their production and output. They're so happy with the system that they are ordering an identical unit for their new facility.



A company that produces and finishes stone composite countertops and sinks was having issues with product damage. The 200 to 1000lb pieces of stone composite are difficult to maneuver during the cutting and polishing procedure and worker safety was a major concern.

Workers had to move the slabs first to a rack for cutting, then to the polishing machines (CNC) and finally to packaging. They were using forklifts, straps, and handcarts for the operation. Not only was the process inefficient and often resulted in damage to the product, but it was extremely dangerous ergonomically.

A free standing workstation bridge crane with a 24' bridge was the solution. The workstation crane offered the most usable area in the location and was more affordable than I-Beam construction. The system can also be modified or added on to later if needed.



600 Fishers Run | Fishers, NY 14453-0596
800-821-0086 | www.gorbel.com