

Case Study... Pedestrian Safety in Warehouses


Customer: IKEA, Jerusalem

Situation:

Within warehouse Supplier Zones forklifts are moving in various directions along the same path as pedestrians. This created a safety hazard in which pedestrians were at high risk of injury. There was no method in which pedestrians could maintain their workflow without traveling through these supplier zones and in the path of forklifts.

Solution:

After using SlowStop Bollards in other locations of the warehouse, they knew the clean look and stopping power of SlowStop would be an ideal solution. Arbel Strauss a direct SlowStop distributor in Israel, installed IronFlex 3" double railing, and since the guarding system is completely modular they were able to create a pedestrian route all along the supplier zone. This created a safe zone for pedestrian traffic to flow through the supplier zones even during high traffic times, without incident.



☎ 210.736.4477

🌐 www.SlowStop.com

✉ info@SlowStop.com

